Oil Field Environmental Incident Summary

Responsible Party: ONEOK Rockies Midstream

Well Operator: ZAVANNA, LLC

Well Name: THELMA 1-21H

Field Name: STOCKYARD CREEK Well File #: 20439

Date Incident: 6/18/2015 Time Incident: 13:00 Facility ID Number:

County: WILLIAMS Twp: 154 Rng: 99 Sec: 28 Qtr: NE NE

Location Description: Lat 48.1253385 long -103.4137003

South of the Thelma 1-21H Location

10 Miles East of Williston on Hwy 1804 and S on 126th Ave Mile

Submitted By: Kim Rudningen Received By:

Contact Person: Kimberly Rudningen

1200 17TH STREET STE 1100

DENVER, CO 80202

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other 1 Barrels

Description of Other Released Contaminant:

Natural gas condensates

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

There are no immediate risks associated with this release

Areal Extent:

The area of surface impact was approximately 3 feet in diameter.

Potential Environmental Impacts:

All standing liquids were removed from the bell hole. There is not potential for surface water impact and the release is contained within the bell hole and pipeline ROW

Action Taken or Planned:

The pipeline has been exposed. Impacted soils were segregated on a tarp and hauled to landfill. Work will continue next week. Any further impacted soils will also be removed to landfill and clean soil will be brought in. The pipeline will be repaired and placed back into service.

Wastes Disposal Location: Waste Management is hauling soil to 13 mile secure landfill, Williston ND.

Agencies Involved:

,,,	-	_	_	4-	_
	n	п	-	то	
v	\sim	u	u	te	v

Date: 6/22/2015 Status: Reviewed - Follow-up Required Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release due to pipeline leak on pipeline ROW. Follow-up is necessary.

Date: 8/17/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 17:18 8/11/2015.

No sign of spill at the time of inspection.

No followup is necessary.